

B2

			ASDA-B2					
						P1-00		1
						P1-01		0 100
10	P+		43	PULSE	1	P1-03		0 10
11	P-		41	/PULSE		P2-10		101 001
13	S+		39	SIGN	2	P1-44		16
14	S-		37	/SIGN		P1-45		1
2	A+	A	21	OA	A	P1-46		2500
3	A-		22	/OA		P2-21		108
4	B+	B	25	OB	B	P2-15		0
5	B-		23	/OB		P2-16		0
6	Z+	Z	13	OZ	C	P2-17		0
7	Z-		24	/OZ				
1	+24V	+24V	11	COM+	DC24V +			
9	0V	24V	14	COM-	DC24V -			
			27	ALRM-	14 (COM-)			
15	ALRM		28	ALRM+				
8	SON		9	SON				
12	BARKE		1	DO4+				
			26	DO4-	14 (COM-)			