

|    |       |      |    |        |        |
|----|-------|------|----|--------|--------|
|    |       |      |    |        |        |
|    |       |      |    |        |        |
| 10 | P+    |      | 7  | PULS   | 1      |
| 11 | P-    |      | 8  | /PULS  |        |
| 13 | S+    |      | 11 | SIGN   | 2      |
| 14 | S-    |      | 12 | /SIGN  |        |
| 2  | A+    | A    | 33 | PAO    | A      |
| 3  | A-    |      | 34 | /PAO   |        |
| 4  | B+    | B    | 35 | PBO    | B      |
| 5  | B-    |      | 36 | /PBO   |        |
| 6  | Z+    | Z    | 19 | PCO    | C      |
| 7  | Z-    |      | 20 | /PCO   |        |
| 1  | +24V  | +24V | 47 | 24V IN | +      |
| 9  | 0V    | 24V  |    |        |        |
|    |       |      | 32 | ALM-   | -      |
|    |       |      | 26 | BK -   | -      |
| 15 | ALRM  |      | 31 | ALM+   | D0-1 + |
| 12 | BRAKE |      | 25 | BK+    | D0-2 + |
| 8  | SON   |      | 40 | /S-ON  | D0-3   |

Pn50F

|       |            |        |        |                      |  |
|-------|------------|--------|--------|----------------------|--|
|       |            |        |        |                      |  |
|       |            | +      | -      |                      |  |
| Pn50F | n. ■ 0 ■ ■ | —      | —      | /BK                  |  |
|       | n. ■ 1 ■ ■ | CN1-25 | CN1-26 | CN1-25/CN1-26<br>/BK |  |
|       |            |        |        |                      |  |
|       |            |        |        |                      |  |

|       |             |    |
|-------|-------------|----|
|       |             |    |
| Pn000 | n.0010      |    |
| Pn200 | n.0001      |    |
| Pn201 | 16384       | PG |
| Pn202 | n.1/16384   |    |
| Pn203 | n.1/2500    |    |
| Pn50A | n.8800/8870 |    |
| Pn50B | 8888        |    |
| Pn50C | 8888        |    |
| Pn50D | 8888        |    |
| Pn50E | n.0000      |    |
| Pn50F | n.0100      |    |