

			A4C					
						Pr02		0
10	P+		22	PULSH	1	Pr40		1
11	P-		23	PULSH		Pr41		0 1
13	S+		24	SIGNH	2	Pr42		1
14	S-		25	SIGNH		Pr46		0 1
2	A+	A	15	OA+	A			
3	A-		16	OA-				
4	B+	B	17	OB+	B			
5	B-		18	OB-				
6	Z+	Z	19	OZ+	Z			
7	Z-		20	OZ-				
1	+24V	+24V	1	COM+	+			
9	GND	+24V	13	COM-	-			
8	SON		2	SRV-ON				
15	ALRM		9	ALM+				
12	BRAKE		11	BRKOFF+				